

Model and
Type Cert

<u>Model & T.C. #</u>	<u>STC #</u>	<u>Description</u>	<u>STC Holder</u>
AA; GA Series; Inc.	SA1626NM	Installation of Elec-	NM-S Electronics Int'l
T.C. A11EA, A16EA, A17SO		tronics Int'l Digital EGT/CHT Instruments and accessories. Amended 5/9/93.	5289 N.E. Elam Young Parkway #G200 Hillsboro, OR 97124
G Series, Inc.	SA2190NM	Installation of Elec-	NM Electronics Int'l
AA Series, GA Series, T.C. A11EA, A16EA, A17SO		tronics Int'l Digital Volt/AMP gauges and accessories. Issued 2/16/84.	5289 N.E. Elam Young Parkway #G200 Hillsboro, OR 97124
AA Series Inc.	SA2350NM	Installation of Elec-	NM Electronics Int'l
GA Series T.C.A11EA A16EA, A17SO		tronics International digital carburetor/outside air temperature gauges. Amended 5/26/87.	5289 N.E. Elam Young Parkway #G200 Hillsboro, OR 97124
AA Series, Inc.	SA2693NM	Installation of Elec-	NM Electronics Int'l
GA Series; T.C. A11EA, A16EA, A17SO		tronics International digital volt/amp gauges and accessories. Amended 1/26/88.	5289 N.E. Elam Young Parkway #G200 Hillsboro, OR 97124
GA Series;	SA4302NM	Installation of Elec-	NM-S Electronics Int'l,

Inc.

T.C.A17SO tronics Int'l Digital 5289 N.E. Elam Young
Automatic Engine Analyzer. Parkway #G200
Amended 3/5/93. Hillsboro, OR 97124

AA-1A, AA-1B, SA308EA Installation of A.R.P. EA Alfred R. Puccinelli
AA-5, AA-5A; Industries Inc. carburetor DER 1-145
T.C. A11EA, ice detection system 105AP 36 Bay Drive East
A16EA in single and twin engine Huntington, L.I.,
aircraft and single engine NY 11743
helicopters powered by
Continental, Franklin,
and Lycoming type engines
equipped with Marvel-
Schebler MA-2, MA-3,
MA-3SPA, MA-4, MA-4-5,
MA-6 and HA -6 series
carburetors.
Amended 10/20/78.

AA-1 Series; SA809NW Installation of fixed NW Maynard C. Corsby
T.C. A11EA (flush) cowl flap, nose c/o Ken Blackman
Fld gear strut fairing and Bldg. C-52-1, Paine
retainer. Everett, WA 98204
Issued 7/20/79.

AA-1 Series; SA810NW Installation of main NW Maynard C. Crosby
T.C. A11EA landing gear fairings c/o Ken Blackman

Fld		from the AA-5 series		Bldg. C-52-1, Paine
		aircraft incorporating		Everett, WA 98204
		sheet metal covers over		
		rubber in place of stock		
		rubber parts.		
		Issued 7/20/79.		
AA-1;	SA1010CE	Installation of wing	CE-W	Horton STOL -Craft
T.C. A11EA		leading edge cuffs.		Wellington Municipal
Arpt				
		Amended 8/21/84.		Wellington, KS 67152
AA-1;	SA1410SW	Mitchell automatic flight	SW	Century Flt Systems,
Inc.		system AK301, consisting		F.M. 1195, P.O. Box
T.C. A11EA		of Century I autopilot		Mineral Wells, TX
610				
76067		with optional omni tracker.		
		Reissued 7/10/84.		
AA-1;	SA2104WE	Installation of Brittain	SW	Brittain Industries,
Inc.		Models B2C and BSS flight		P.O. Box 51370
T.C. A11EA		control systems.		Tulsa, OK 74151
		Reissued 10/20/72.		
AA-1 Series;	SA3565SW	Modification of torque	SW	Frank B. Johnston
T.C. A11EA		tube assembly.		Box 701067
		Amended 12/15/89.		San Antonio, TX
78270-1067				

AA-1 Series; Inc.	SA5987SW	Installation of main	SW	Dallas Metroplex Avn
T.C. A11EA		landing gear fairing		2905 Hilltop Lane
		clean-up kit.		Plano, TX 75075
		Issued 7/30/85.		
AA-1, AA-1A; T.C. A11EA	SA8431SW	Installation of R15VON	SW	Tovya Group, Inc.
		alternator control unit.		dba Zeftronics
		Amended 1/6/94.		1622 E. Whaley St.
6830				Longview, TX 75601-
AA-1 Series, Inc.	SA5159NM	Installation of chip	NM	Northwest Aircraft,
AA-5 Series, 111; Airport		detector system.		Tacoma Narrows
T.C. A11SO,		Amended 10/21/91.		1520 26th Avenue NW
A16EA, A11EA				Gig Harbor, WA 98335
AA-1, AA-1A, AA-1B; T.C. A11EA	SA1313CE	Chrome-plated brake disc	CE	Engineering Plating
		installation.		and Processing, Inc.
		Amended 6/20/77.		641 Southwest Blvd
66103				Kansas City, KS
AA-1, AA-1A, AA-1B; T.C. A11EA	SA2169NM	Installation of a Sen-	NM	Maynard C. Crosby
		senich 72 CK series		P.O. Box 2361
		propeller, Gulfstream		Everett, WA 98203
		American spinner (P/N		
		506006-50), engine oil		

cooler on a Lycoming 0-
235-C2C engine.
Reissued 4/29/91.

AA-1, AA-1A, SA3234WE Installation of Piper oil WE Acft Maintenance Svc
AA-1B; cooler and associated 7950B Joe Crosson
Drive installation components. Santee, CA 92071
T.C. A11EA Issued 7/8/76.

AA-1, AA-1A, SA4106SW Increase gross weight to SW Fletcher Aviation
AA-1B; 1560 lbs. for AA-1, 1560 8904 Randolph
T.C. A11EA lbs. for AA-1A, and 1600 Houston, TX 77061
lbs. for AA-1B.
Reissued 3/20/89.

AA-1, -1A, -1B; SA4994NM Installation of split NM Aviation Development
Corp nose bowl. 1305 NW 200th
T.C. A11EA Issued 12/5/90. Seattle, WA 98177

AA-1, AA-1A, SA868GL Modify airplane to fly CE-C EAA Avn Foundation,
Inc. on unleaded automotive Wittman Field
AA-B, AA-1C; gasoline, 87 minimum anti Oshkosh, WI 54903-
T.C. A11EA 3065 knock index.
Issued 2/12/85.

AA-1, AA-1A, SA10NW Installation of VA-3 NM James L. Fletcher

AA-1B;		fiberglass wheel fairings.		8904 Randolph Street
T.C. A11EA		Reissued 12/30/92.		Houston, TX 77061
AA-1, AA-1A,	SA11NW	Installation of VA-2	NM	James L. Fletcher
AA-1B;		wheel fairings.		8904 Randolph Street
T.C. A11EA		Reissued 12/30/92.		Houston, TX 77061
AA-1, AA-1A,	SA66NW	Installation of Van's	NM-S	James L. Fletcher
AA1B, AA-5;		Aircraft model BA-4		9000 Randolph Street
T.C. A11EA		fiberglass wheel fairings.		Houston, TX 77061
		Amended 9/23/94.		
AA-1, AA-1A,	SA991NW	Engine mount, cowling,	NM	Kennis G. Blackman
AA-1B, AA-1C;		carburetor air on Lycoming		7305 97th Avenue,
S.E.				
T.C. A11EA		O-235-L2C (modified by STC		Snohomish, WA 98290
		SE792NW) and Sensenich		
		72CK-S12-0-57 propeller.		
		Issued 7/17/80.		
AA-1, AA-1A,	SA1009NW	Grumman American AA-5A	NM	Kennis G. Blackman
AA-1B, AA-1C;		dorsal fin.		7305 97th Avenue,
S.E.				
T.C. A11EA		Issued 8/21/80.		Snohomish, WA 98210
AA-1, AA-1A,	SA1209NW	Relocation of battery	NM	Maynard C. Crosby
AA-1B, AA-1C;		from forward face of fire-		P.O. Box 2361
T.C. A11EA		wall to aft baggage		Everett, WA 98203
		compartment bulkhead.		

AA-1, AA-1A, AA-1B, AA-1C; T.C. A11EA	SA2267SO	Installation of an instrument panel overlay and glove box door. Issued 3/7/88.	CE-A	Forest Butler 2465 Gum Creek Road Oxford, GA 30267
AA-1, AA-1A, AA-1B, AA-1C; T.C. A11EA	SA2274SO	Installation of a glare shield assembly. Issued 3/7/88.	CE-A	Forest Butler 2465 Gum Creek Road Oxford, GA 30267
AA-1, AA-1A, AA-1B, AA-1C; T.C. A11EA	SA2477SW	Installation of Lycoming 0-320 or 0-290 engine. Reissued 3/20/89.	SW	Fletcher Aviation 8904 Randolph Houston, TX 77061
AA-1, AA-1A, Aviation AA-1B, AA-1C; Drive T.C. A11EA	SA7952SW	Installation of conven- tional landing gear. Reissued 1/14/93.	SW	Dallas Metroplex 14902 Forest Lodge Houston, TX 77070
AA-1, AA-1A, Aviation AA-1B, AA-1C; Drive T.C. A11EA	SA7974SW	Installation of wheel pant fairings. Amended 3/25/92.	SW	Dallas Metroplex 14902 Forest Lodge Houston, TX 77070
AA-1, AA-1A, -1B, -1C; T.C. A11EA	SA4387NM	Installation of Lycoming 0-320-A, C, or E series engine and a Sensenich 74DM6-0-58/64 or 74DM7- 0-58/64 propeller.	NM	Air Mods, NW P.O. Box 8 Snohomish, WA 98290

Amended 6/13/91.

AA-1, -1A, -1B, -1C; T.C. A11EA	SA4722NM	Installation of a hat shelf in the aft baggage compartment. Issued 4/17/89.	NM	Air Mods, NW P.O. Box 8 Snohomish, WA 98290
AA-1, -1A, -1B, Corp -1C; T.C. A11EA	SA4917NM	Modification of upper engine cowl. Issued 4/16/90.	NM	Aviation Development 1305 NW 200th Seattle, WA 98177
AA-1, -1A, -1B, Inc. AA-5, -5A, -5B; T.C. A11EA, A16EA	SA1745SO	Installation of Appal- achian Access. stainless steel brake rotors, P/N 75-20. Reissued 2/6/95.	CE-A	Aviation Products, 1400 E South Blvd Montgomery AL 36116
AA-1, -1A, -1B, Corp -1C, AA-5, -5A, -5B; T.C. A11EA, A16EA	SA4172NM	Installation of oil filter. Amended 10/4/95.	NM	Aviation Development 1305 N.W. 200th Seattle, WA 98177
AA-1, AA-1A, opment -1B, -1C, -5, -5A, -5B; AG-5B;	SA5934NM	Installation of cockpit sunvisor. Amended 8/31/95.	NM	Rosen Product Devel- P O Box 21636 Eugene, OR 97402

T.C. A16EA,

A11EA

AA-1, AA-1A, B, SA00187AT Installation of carbon CE-A Aviation Products,
Inc.
AA-5, AA-5A, B; steel brake discs, P/N 1400 E South Blvd
T.C. A11EA, AA-20. Montgomery, AL 36116
A16EA Reissued 11/14/94.

AA-1; SA2105WE Installation of Model NM K S Avionics
T.C. A11EA EGT-3 exhaust gas temp- 18145 Judy Street
94546 erature monitor (with Castro Valley, CA
rising temperature alarm).
Issued 2/9/70.

AA-1, -1A, -1B, SA2557NM Installation of KS NM KS Avionics, Inc.
-1C, AA-5, -5A, Avionics EGT/CHT-2() 25216 Cypress Avenue
-5B, GA-7, combined exhaust gas and Hayward, CA 94544
T.C. A11EA, cylinder head temperature
A16EA, A17SO monitoring system.
Issued 4/29/85.

AA-1, AA-1A, SA4849SW Install fuel flow trans- SW Dallas Metroplex Avn
Inc. ducer in fuel line and 2905 Hilltop Lane
AA-1B, AA-1C, install fuel flowmeter/ Plano, TX 75075
AA-5, AA-5A, totalizer in aircraft
AA-5B Series; Amended 10/26/84.
T.C. A11EA

AA-1 (1969 and On), AA-1A (1969 Svc and on), AA-1B (1969 and on), AA-5 (1972, 1973 and 1974 only); T.C. A16EA	SA69NW	Installation of Matney's engine charge air-air filter assembly. Amended 10/8/74.	NW	D.H. Matney d/b/a Matney's Acft 24415 116th S.E. Kent, WA 98031
AA-1, AA-1A, pany AA-1B, AA-1C, Drive AA-5; T.C. A11EA, A16EA	SA71GL	Installation of air filters. Amended 4/17/95.	NM-L	Brackett Acft Com- 7045 Flightline Kingman AZ 86401
AA-1, AA-1B, AA-1C, AA-5, AA-5A, AA-5B; 11581 T.C. A11EA, A16EA	SA191NE	Replace original brake discs with discs modified in accordance with Roland Longarzo procedure. Reissued 10/4/84.	NE	Orel Aviation, Inc. 218 Hollywood Avenue Valley Stream, NY
AA-1, AA-1A, AA-1B, AA-5, AA-5A, AA-5B; T.C. A11EA, A16EA	SA330NE	Replace original brake discs w/William C. Roberts stainless steel discs, P/N 201-120-SS. Amended 10/15/92.	NE	William C. Roberts 5 Lynbrook Lane Doylestown, PA 18901

AA-1, AA-1A, AA-5; Road T.C. A11EA, 0684 A16EA	SA615EA	Installation of Whelen anti-collision strobe light system, Models HD, HR or HS (-14 (14V) or -28 (28V)), as replacement for originally installed anti- collision lights. Amended 7/16/91.	NE	Whelen Engr Co. Inc. Route 145, Winthrop Chester, CT 06412-
AA-1, AA-1A; AA-5; Road T.C. A11EA, 0684 A16EA	SA800EA	Installation of aviation white anti-collision strobe lights Whelen Models A429, A430, A434, A450, A408 (white), A408R /W or A470R/W (red/white), A500, A625 or A650 and associated power supplies or Model SA strobe light system. Amended 11/22/93.	NE	Whelen Engr Co. Inc. Route 145, Winthrop Chester, CT 06412-
AA-1, -1A, -1B, -1C, AA-5, -5A, -5B; 92615 T.C. A11EA, A16EA	SA2586NM	Installation of J.P. Instruments exhaust gas and/or cylinder head temperature monitoring systems.	NM	J.P. Instruments P.O. Box 7033 Huntington Beach, CA

Issued 8/14/85.

AA-1, -1A, -1B, SA2683NM Installation of Precise NM Precise Flight, Inc.
-1C, -5, -5A, Flight, Inc. stand-by 63120 Powell Butte
Rd
-5B, vacuum system (SVS) Model Bend, OR 97701
T.C. A11EA, SVS III.
A16EA Amended 4/26/90.

AA-1, AA-1A, SA2844CE Installation of a plastic CE-W Air Transport Inc.
AA-5; cap enclosure over the 1015 N. Carlton
T.C. A11EA, anti-collision strobe light Liberal, KS 67901
A16EA system.
Issued 7/29/92.

AA-1, -1A, -1B, SA4708NM Bolt installation in nose NM Air Mods NW
-1C, -5, -5A, gear torque tube assembly. P.O. Box 8
-5B; Issued 2/28/89. Snohomish, WA 98290
T.C. A11EA,
A16EA

AA-1A, AA-1B, SA4740NM Installation of a landing NM Joseph G. Breuer
-1C, AA-5, -5A, light in the left wing tip 1305 NW 200th
5B; or in both wing tips. Seattle, WA 98177
T.C. A11EA Amended 3/1/90.

AA-1, -1A, -1B, SA5775NM Replacement of rudder tip NM Aviation Development
Corp
-1C, AA-5, -5A, with Aviation Red Lexan 1305 NW 200th
-5B; tip with flashing anti Seattle, WA 98177

T.C. A11EA, A16EA		collision light located inside.	
AA-1, -1A, -1B, -1C, AA-5, RD AA-5A, AA-5B, GA-7; T.C. A17SO, A16EA, A11EA	SA4005NM	Installation of Precise Pulsite control unit in landing taxi system. Amended 10/16/92.	NM-S Precise Flight, Inc. 63120 Powell Butte Bend, OR 97701
AA-1, AA-1A, AA-1B, AA-1C; T.C. A11EA 44062	SA00024NY	Installation of Airwolf remote mounted engine oil filter kit AFC-8007 on single and multi-engine fixed wing light aircraft incorporating Lycoming reciprocating engines or 450 horsepower or less. Amended 11/22/94.	NE-NY Airwolf Filter Corp. 15401 Madison Road Middlefield, OH
AA-1 Series, Ltd. AA-5 Series, GA-7; T.C. A11EA, A16EA, A17SO	SA1418SO	Replacement of rotor vanes in airborne 211CC and 212CW vacuum pumps. Issued 3/10/83.	CE-A U.S. Air Source, 3640 Atlanta Highway Athens, GA 30604
AA-1, AA-5;	SA1512WE	Installation of exhaust	NM K S Avionics

T.C. A11EA, A16EA 94546		gas temperature monitoring systems Model EGT-1. Amended 8/23/74.	18145 Judy Street Castro Valley, CA
AA-1, AA-1, GA-7; T.C. A17SO, A16EA, A11EA	SA5656NM	Installation of burglar alarm system. Amended 7/21/93.	NM-S Harold S. Thompson P.O. Box 2361 Gig Harbor, WA 99206
AA-1, -1A, -1B, -1C; AA-5, -5A, #G200 -5B; T.C. A16EA	SA5924NM	Installation of RPM instrument. Amended 6/3/94.	NM-SE Electronics Interna- tional 5289 Elam Young Pkwy Hillsboro, OR 97124
AA-1, -1A, -1B, -1C; AA-5, -5A, #G200 -5B; T.C. A16EA	SA5925NM	Installation of oil pressure/temperature instrument. Amended 6/3/94.	NM-SE Electronics Interna- tional 5289 Elam Young Pkwy Hillsboro, OR 97124
AA-1, -1A, -1B, -1C, AA-5, -5A, -5B; T.C. A11EA, A16EA	SA00079SE	Addition of a low oil pressure warning light to the Oberg oil filter installed per STC SA4172NM. Amended 9/7/94.	NM-SE Aviation Development 1305 NW 200th St Seattle, WA 98177

AA-1, AA-1A, SA1735GL Installation of Master Nag CE-C Gosman Aircraft
-1B, -1C; AA-5, warning system. 528 Walnut Dr.
-5A, -5B; Amended 3/21/94. Madison, IN 47250

T.C. A11EA,
A16EA

AA-1, -1A, SA00061LA Installation of JPI NM-L J P Instruments
-1B, -1C, AA-5, digital tachometer. 9621 Bay Meadow Dr
-5A, -5B; Issued 3/29/95. Huntington Beach CA
92646

T.C. A11EA,
A16EA

AA-1, AA-1A, Supplies, Inc.	SA00081NY	Installation of carburetor	NE-NY	Iceman Aviation
AA-1B, AA-1C, Avenue		ice detector.		160 Industrial
AA-5, AA-5A,		Amended 12/7/95.		Carlton Place
AA-5B;				Canada K7C 3T2
T.C. A11EA, A16EA				
AA-1, AA-1A, ited	SA00215NY	Installation of Model	NE-NY	CAVU Products Lim-
AA-1B, AA-1C;		AM100 AVMIX engine fuel		2325 Mountland Drive
AA-5, AA-5A, Ontario		/air mixture setting		Petersborough,
AA-5B, AG-5B;		system.		Canada K9K 1W3
T.C. A11EA, A16EA		Amended 8/14/95.		
AA-1, AA-1A, tional	SA00068SE	Installation of fuel	NM-S	Electronics Interna-
AA-1B, AA-1C,		flow pressure/instruments.		12620 SW 231st Place
AA-5, AA-5A, 97123		Issued 3/31/94.		Hillsboro, Oregon
AA-5B, GA-7;				
T.C. A11EA, A16EA, A17SO				
AA-1C;	SA761NE	Modifications to lower	NE	William J. McKay
T.C. A11EA		engine cowling with		LaRosa Ave.
		landing gear boot adapter		Gloucester, MA 01930
		and change to upper engine		
		cowling with a split nose		

bowl configuration.

Issued 6/18/90.

AA-1C; SA762NE Installation of pilot and NE William J. McKay
T.C. A11EA copilot control column LaRosa Ave.
stick type grip. Gloucester, MA 01930
Issued 6/18/90.

AA-1C; SA2129NM Installation of a NM Kennis G. Blackman
T.C. A11EA Lycoming 0-320-E2G engine, 7305 97th Avenue SE
AA-5A engine mount, cowl- Snohomish, WA 98290
ing, air induction, and a
McCauley 1C172/SBTM/7359
propeller.
Reissued 4/8/91.

AA-1C; SA5197NM Installation of split NM Aviation Development
Corp cowl nose bowl. 1305 NW 200th
T.C. A11EA Issued 11/4/91. Seattle, WA 98117

AA-1C Utility SA3695WE Installation of Lycoming WE Aero-Training, Inc.
Category; 0-235-C2C engine and 89 John Glenn Drive
T.C. A11EA McCauley 1A105/SCM7154 Concord, CA 94520
propeller. No instal-
lation data required.
Placards required with
this installation:
At the fuel filler caps -

"80/87 MIN OCTANE AVGAS"

Issued 7/7/78

AA-5; SA1169NW Installation of a Lycoming NM Maynard C. Crosby
T.C. A16EA 0-360-A4K engine and a P.O. Box 2361
Sensenich 76EM8S10-0-63 Everett, WA 98203
propeller.
Reissued 4/29/91.

AA-5; SA1472SW Mitchell automatic flight SW Century Flt Systems,
Inc. system AK373 consisting F.M. 1195, P.O. Box
T.C. A16EA 610 of Century I autopilot Mineral Wells, TX
76067 with optional omni tracker.
Reissued 7/10/84.

AA-5; SA1486SW Mitchell automatic flight SW Century Flt Systems,
Inc. system AK374 consisting F.M. 1195, P.O. Box
T.C. A16EA 610 of Century IIB autopilot Mineral Wells, TX
76067 with optional radio coupler.
Reissued 7/10/84.

AA-5; SA2125NM Installation of Lycoming NM Maynard C. Crosby
T.C. A16EA 0-360-A4M engine and P.O. Box 2361
Sensenich 76EM8S10-0-60 Everett, WA 98203
propeller.

Reissued 4/29/91.

AA-5; T.C. A16EA	SA4721NM	Installation of SynCon alarm system. Amended 5/8/90.	NM	SynCon, Inc. P.O. Box 188 Loon Lake, WA 99148
AA-5; T.C. A16EA	SA4968NM	Installation of a Lycoming 0-320-E2D engine equipped with a Sensenich 4DM6- 0-58 propeller reduced to 73" diameter. Issued 8/14/90.	NM	Mrs. Anne Barth 16441 8th Avenue S. Seattle, WA 98148
AA-5 Series; T.C. A16EA 78270-1067	SA3564SW	Modification of torque tube assembly. Amended 12/15/89.	SW	Frank B. Johnston Box 701067 San Antonio, TX
AA-5, AA-5A; T.C. A16EA Avenue	SA420CH	Install Unison Limited Authority Spark Advance Regulator ignition system. Reissued 2/14/96.	CE-C	Unison Industries 530 Blackhawk Park Rockford, IL 61104
AA-5, AA-5A; Inc. T.C. A16EA	SA1965CE	Operation on unleaded and/or leaded automotive gasoline. Amended 11/27/85.	CE-W	Petersen Aviation, Route 1, Box 18 Minden, NE 68959

AA-5, AA-5A; T.C. A16EA	SA1186NW	Installation of a Lycoming 0-360-A4K engine, a McCauley 1A170FFA/7563 or a Sensenich 76EM8S10- 0-60 thru -65 propeller and associated systems. Amended 4/29/91.	NM	Maynard C. Crosby P.O. Box 2361 Everett, WA 98203
AA-5, AA-5A; T.C. A16EA	SA1299NW	Installation of a Mc- Cauley propeller on Lycoming 0-320-E2G engine.	NM	Maynard C. Crosby P.O. Box 2361 Everett, WA 98203
AA-5A; T.C. A16EA	SA1767NM	Alteration of the oil cooler and air induction system. Reissued 4/29/91.	NM	Maynard C. Crosby P.O. Box 2361 Everett, WA 98203
AA-5, -5A, -5B; Inc. T.C. A16EA 18419	SA540NE	Installation of an aft baggage compartment auxiliary 18 gallon fuel tank and transfer system to the right wing tank. Issued 10/14/87.	NE	O&N Aircraft Mod., P.O. Box 292 Seaman's Airport Factoryville, PA
AA-5, AA-5A; Overhaul T.C. A16EA 344B	SA683NE	Installation of Lycoming Model 0-320-E2G engine	NE	Precision Engine Inc. Hammonton Arpt, Box

that has been converted
to high compression IAW
STC SE682NE amended
10/27/89.
Amended 11/1/89.

AA-5, AA-5A, SA867GL Modify airplane to fly CE-C EAA Avn Foundation,
Inc. Wittman Field
AA-5B; on unleaded automotive
T.C. A16EA gasoline, 87 minimum anti- Oshkosh, WI 54903-
3065 knock index.

Issued 2/12/85.

AA-5, -5A, -5B; SA2268SO Installation of an CE-A Forest Butler
T.C. A16EA instrument panel overlay 2465 Gum Creek Road
and glove box door. Oxford, GA 30267
Issued 3/7/88.

AA-5, AA-5A, SA1133SO Installation of an ad- CE-A Aero Trim, Inc.
AA-5B, AG-5B; justable trim tab on 1130 102 Street
left aileron. Bay Harbor, FL 33154
Amended 1/24/91.

AA-5, -5A, -5B; SA2275SO Installation of a glare CE-A Forest Butler
T.C. A16EA shield assembly. 2465 Gum Creek Road
Issued 3/7/88. Oxford, GA 30267

AA-5, AA-5A, SA3031SW-D Mitchell automatic SW Century Flt Systems,
Inc.

AA-5B; 610		flight system AK514		F.M. 1195, P.O. Box
T.C. A16EA 76067		consisting of Century I autopilot with omni tracking system. Reissued 6/21/84.		Mineral Wells, TX
AA-5, AA-5A, Inc.	SA3032SW-D	Mitchell automatic flight	SW	Century Flt Systems,
AA-5B; 610		system AK515 consisting of		F.M. 1195, P.O. Box
T.C. A16EA 76067		Century IIB autopilot with optional radio coupler. Reissued 6/21/84.		Mineral Wells, TX
AA-5, -5A, -5B; T.C. A16EA	SA3760NM	Installation of single piece frameless windshield. Issued 2/19/88.	NM	Cee Bailey's Aircraft Plastics 2955 Junipero Avenue Long Beach, CA 90806
AA-5, AA-5A, AA-5B; T.C. A16EA Complex 76067	SA5386SW-D	Installation of 40/50 single and two axis auto- matic flight guidance systems. Reissued 5/12/89.	SW	S-TEC Corporation Rt 4, Bldg 946 Wolters Industrial Mineral Wells, TX
AA-5, AA-5A, AA-5B;	SA8031SW	Installation of Zeft- ronics alternator con-	SW	Tovya Group, Inc. dba Zeftronics

T.C. A16EA 6830		troller unit P/N R15100 or R15V00. Amended 1/6/94.		1622 E. Whaley St. Longview, TX 75601-
AA-5, AA-5A, Inc. AA-5B, AG-5B; Blvd T.C. A16EA	SA6016NM	Installation of an electronic digital engine tachometer, Horizon Model P-1000, P/N P100050-(). Issued 5/18/93.	NM-L	Horizon Instruments, 556 S. State College Fullerton, CA 92631
AA-5A; T.C. A16EA Way	SA4966NM	Installation of a Lycoming NM IO-540-D4A5 engine and a Hartzell HC-C2YK-8477-7 propeller. Issued 9/4/90.		John A. Coze 2001 Sailor Claim Gold River, CA 95670
AA-5A; T.C. A16EA	SA5452NM	Installation of a Lycoming NM-L IO-360-C1C6 engine and Hartzell HC-C2YK-1BF/ F7666A-2 propeller. Issued 7/3/91.		Peter Otten P.O. Box 8451 La Jolla, CA 92038
AA-5A, AA-5B; T.C. A16EA 946	SA5372SW-D	Installation of S-TEC System 60 two axis auto- matic flight guidance system, Model ST-278.	SW	S-TEC Corporation Route 4, Building Wolters Ind Complex Mineral Wells, TX

76067

Reissued 10/10/86.

AA-5A, AA-5B; T.C. A16EA 946	SA5376SW-D	Installation of S-TEC System 60 pitch stabil- ization system, Model ST-279.	SW	S-TEC Corporation Route 4, Building Wolters Ind Complex Mineral Wells, TX
------------------------------------	------------	--	----	--

76067

Issued 2-15-85.

AA-5A, AA-5B; T.C. A16EA 946	SA6089SW-D	Installation of S-TEC System 65 two axis auto matic flight guidance system, Model ST-381.	SW	S-TEC Corporation Route 4, Building Wolters Ind. Complex Mineral Wells, TX
------------------------------------	------------	--	----	---

76067

Issued 10/10/86.

AA-5A, AA-5B, Systems AG-5B; T.C. A16EA	SA8505SW-D	Installation of a Century Automatic Flight System, Model AK1022 consisting of a Century 2010/2050/2051 autopilot.	SW	Century Flight F.M. 1195 P O Box 610 Mineral Wells TX
--	------------	---	----	--

76068

Issued 9/20/95.

AA-5, AA-5A, AA-5B; 946 T.C. A16EA	SA5387SW-D	Installation of S-TEC System 60 single axis automatic flight guidance	SW	S-TEC Corporation Route 4, Building Wolters Ind Complex
---	------------	---	----	---

76067		system, model ST -277.		Mineral Wells, TX
		Issued 3/25/85.		
AA-5B; Corp.	SA157NE	Installation of graphic	NE	Insight Instrument
T.C. A16EA Station		engine monitor system		Box 194, Ellicott
		Model GEM-602, S/N 403		Buffalo, NY 14205
		and subsequent.		
		Amended 1/29/88.		
AA-5B;	SA1195NW	Installation of Sensenich	NM	Fletchair, Inc.
T.C. A16EA		76EM8S10-0-60 thru -65		7786 Braniff Street
		propellers on a Lycoming		Houston, TX 77061
		0-360-A4K engine.		
AA-5B; Products	SA2593NM	Installation of Hoskins	NM-L	Simmonds Precision
T.C. A16EA		Model CFS-1000A, -1001A,		BFGoodrich Aerospace
		FT-100, or FT-101 fuel		100 Panton Rd
		flow indicating system.		Vergennes VT 05491
		Reissued 1/30/96.		
AA-5B;	SA2620NM	Modify engine baggles and	NM	Maynard C. Crosby
T.C. A16EA		relocate oil cooler to		P.O. Box 2361
		above and behind the left		Everett, WA 98203
		hand rear cylinder on		
		Lycoming 0-360-A4K engine		
		with Sensenich 76EM8S10-0		
		-63 propeller.		

Reissued 4/29/91.

AA-5B; SA3301WE Installation of Model WE K S Avionics, Inc.
T.C. A16EA EGT-1 exhaust gas temp- 18145 Judy Street
94546 erature monitoring system. Castro Valley, CA

Issued 11/23/76.

AA-5B; SA3309WE Modification of primary NM Astronautics Corp.
T.C. A16EA control system by addition of America
of rudder - aileron inter- 2416 Amsler Street
connect and installation Torrance, CA 90505
of Pathfinder autopilot

systems and/or pitch trim
systems.

Issued 1/27/77.

AA-5B; SA3326NM Install Sensenich Prop- NM Air Mods N.W.
T.C. A16EA eller model 76EM8S10-0 P.O. Box 8
(60" to 63" pitch, Snohomish, WA 98290
inclusive) and Gulfstream
Aerospace spinner assembly,
Kit Part Number SK143-2.

Issued 2/7/86.

AA-5B; SA3344NM Relocation of oil cooler. NM Kennis G. Blackman
T.C. A16EA Issued 4/3/86. P.O. Box 8
Snohomish, WA 98290

AG-5B; T.C. A16EA Complex 76067	SA7205SW-D 	Installation of S-TEC System 60 two axis auto- matic flight guidance system, Model ST-456. Reissued 9/27/90.	SW 	S-TEC Corporation Rt 4, Bldg 946 Wolters Industrial Mineral Wells, TX
AG-5B; T.C. A16EA 946 76067	SA7211SW-D 	Installation of S-TEC System 60 single axis automatic flight guidance system, model ST-277. Reissued 10/15/90.	SW 	S-TEC Corporation Route 4, Building Wolters Ind Complex Mineral Wells, TX
AG-5B; T.C. A16EA Complex 76067	SA7212SW-D 	Installation of S-TEC system 60 pitch stab- ilization system. Reissued 10/19/90.	SW 	S-TEC Corporation Rt 4, Bldg 946 Wolters Industrial Mineral Wells, TX
AG-5B; T.C. A16EA Complex 76067	SA7213SW-D 	Installation of S-TEC System 40/50 single and two axis automatic flight guidance systems, Model ST-458-40/50. Reissued 9/28/90.	SW 	S-TEC Corporation Rt 4, Bldg 946 Wolters Industrial Mineral Wells, TX

AG-5B; tion	SA00058WI-D	Installation of Bendix/ King KAP 100/KAP 150/KFC 150 automatic flight control systems with optional KAS297B altitude /vertical speed selector. Issued 4/30/93.	SW	King Radio Corpora- 400 N. Rogers Road Olathe, KS 66062
T.C. A16EA				
GA-7; T.C. A17SO	SA1425CE	Install King KFC-200 automatic flight control system. Issued 7/14/78.	CE-W	King Radio Corp. 400 N. Rogers Rd Olathe, KS 66061
GA-7; Inc. T.C. A17SO 610 76067	SA3235SW-D	Mitchell automatic flight system AK634 consisting of Century IV autopilot or AK634FD consisting of Century IV flight director autopilot with remote annunciator. Reissued 12/7/83.	SW	Century Flt Systems, F.M. 1195, P.O. Box Mineral Wells, TX
GA-7; Inc. T.C. A17SO 610 76067	SA3236SW-D	Mitchell automatic flight system AK634 consisting of Century III autopilot with	SW	Century Flt Systems, F.M. 1195, P.O. Box Mineral Wells, TX

optional radio coupler and
glide slope coupler.

Reissued 12/7/83.

GA-7; SA3237SW-D Installation of Mitchell SW Century Flt Systems,
Inc. automatic flight system F.M. 1195, P.O. Box
T.C. A17SO 610 Model AK636, consisting of Mineral Wells, TX
76067 a Century IIB autopilot
with optional radio coupler.
Reissued 12/7/83.

GA-7; SA3238SW-D Mitchell command electric SW Century Flt Systems,
Inc. trim AK637. F.M. 1195, P.O. Box
T.C. A17SO 610 Reissued 12/7/83. Mineral Wells, TX
76067

GA-7; SA289CH Installation of inline CE-C Aerotech Components
T.C. A17SO pneumatic air filter, P/N P O Box 421
CV1J4. Valley City OH 44280
Issued 2/2/95.

GA-7; SA00563AT Installation of Appa- CE-A Aviation Products,
Inc. lachian Accessorie carbon 1400 E South Blvd
T.C. A17SO steel brake discs, P/N Montgomery AL 36116
AA-22.
Reissued 1/24/95.

